



Simple weighing scale **OWNER'S MANUAL**







CONTENTS

| PRECAUTIONS | 4 |
|----------------------------|----|
| PREFACE | 6 |
| NAMES AND FUNCTIONS | 6 |
| OPERATIONS | 8 |
| 1. Simple Weighing Mode | 8 |
| 2. Weighing with Tare | 8 |
| 3. Changing Unit of Weight | ę |
| 4. Hold Function | ç |
| 5. Comparator Function | 10 |
| 6. Counting Function | 11 |
| 7. Setup Mode | 13 |
| 8. Interface in Detail | 15 |
| BATTERY MAINTENACE | 17 |
| ERROR MESSAGE | 17 |
| SPECIFICATIONS | 18 |



Warning


Precautions when installing the scale. To ensure that you get the most from your scale, please follow these instruction.

| Precautions when installing the scale | . 10 ensure | e that you get the most from your scale, please follow these instruction. |
|---------------------------------------|-------------|--|
| | | Do not disassemble the scale. When any damage or defect occurs, contact your CAS authorized dealer immediately for proper repair. |
| | > | Do not overload beyond the maximum weight limit. |
| | | Scale must be grounded to minimize electricity static. This will minimize defect or electric shock. |
| | > | Do not pull the plug by its cord when unplugging. Damaged cord could cause electric shock or fire. |
| | | To prevent from fire occurring, Do not place or use the scale near flammable or corrosive gas. |
| | > | To reduce electric shock or incorrect reading, Do not spill water on the scale or place it in humid condition. |
| | | Avoid placing the scale near heater or in direct sunlight. |
| | > | Insert plug firmly to wall outlet to prevent electric shock. |
| | | Use proper Adapter. Incorrect adapter could damage the scale. |

Attention

Make sure to plug your scal into the proper power outlet.

For maximum performance, plug into a power outlet 30 minutes before the usage for warm up.



PREFACE

Thank you for purchasing CAS SWII series.

These series have been designed with CAS reliability, under rigid quality control and with outstanding performance. Your special departments can enjoy these high quality reliable CAS products.


We believe that your needs will be satisfied and you will have proper reliability.

This manual will help you with proper operation and care of the SWII.


Please keep it handy for future reference.

NAMES AND FUNCTIONS

OVERALL VIEW



DISPLAY &



KEY FUNCTIONS

| KEYS | FUNCTIONS |
|-----------------|--|
| UNIT | Used to set the zero point. |
| FT∢ HOLD | Used to input or cancel the weight of tare. |
| | Used to change the unit of weight, and shown as following sequence on the display. [kg] \rightarrow [WL on or off] \rightarrow [PCS] \rightarrow [kg] |
| Fn | Used to select and hold or unit conversion function |
| + 1 UNIT | Used to convert the unit of weight. |
| + HOLD | Used to make the weight of commodity stable. This weight is average value. |

OPERATIONS

- Turn on the ON/OFF switch. Then, the display will show all the segments and count up "9" to "0".
- When the weight becomes stable the display shows the stable sign (0) on.
- You may need to make it "0.000" by pressing key unless the display indicate "0.000" under the empty platter.

1. Simple Weighing Mode





1 Place a commodity on the platter.





2 Remove the commodity from the platter.

2. Weighing with Tare

- TARE means the weight of container being used for a commodity.
- TARE key function is to subtract the weight of the container from full weight loaded.





1) Place a container on the platter.





2 Press the HOLD ke





③ Place a commodity into the container, then the display will show only the weight of the commodity.





④ Remove container and commodity, then the display will show the weight of the container with "-" symbol.





⑤ Press the HOLD key, then display will show the "0.000"

the "0.000".


3. Changing Unit of Weight

4. Hold Function





① When the weight is unstable, press the key



 $\ 2$ " -Fn- " will be displayed





3 Press the key. Then "hOLd" will be displayed twice



Then average value will be show twice And the "hOLd " function will be removed automatically

5. Comparator Function - HI / LOW Limit Setting





① Press the wey until the display shows "WL OFF". "WL OFF" means that comparator function is not activated.





② Press key to activate this function.

The display shows "WL ON".





③ Press key once to set up the low limit. The display shows "1.000" and the first number flashes











© Press will key to set up HIGH limit. The display shows "2.000" and you can change these numbers by pressing key.

If you want to move to next digit you can go by pressing key.





- ⑥ If you set up HIGH limit you can go out by pressing key, and "End" message on the display.
- ⑦ If you set up HIGH limit and LOW limit incorrectly, "Err" will be shown on the display. Then you may need to set it up again. For example, setting LOW LIMIT=2.990 kg and HIGH LIMIT=1.990 kg this is incorrect setting because HIGH limit is lower than the LOW limit. When HIGH and LOW limit are set as the same or above maximum capacity it still shows "Err" message.






- ® Suppose that the HIGH limit and LOW limit are set up as 2.990kg and 1,990kg respectively.
- If the weight loaded is 2kg between HIGH and LOW limit the display shows "OK" and the


scale continues to beep slowly. If the weight loaded is above 2.990kg, HIGH limit, the scale continues to beep rapidly.

6. Counting Function

Counting without Tare



Counting with Tare







® When you try to set the number of sample unit at the ③ stage, the display may show "LACK" message shortly. The result of counting may be incorrect in the

The result of counting may be incorrect in the following cases.

- a. unit weight ≤1/2 e *
- b. weight loaded ≤2% of maximum weighing capacity.

* "e" value may be various on capacity of product model.

Please refer to "SPECIFICATION" on page 15. For example, a product model which capacity is 3.000 kg has 1g as "e" value

7. Setup Mode

This function is helpful to setup user setting, which is about Backlight and communication. The following is the setting procedure of Backlight On/Off & RS-232C communication.





TABLE 1.

| MENU | DISPLAY | DESCRIPTION |
|-----------|---------------|---|
| Backlight | bi-of > | Do not use a back-light |
| | <u> </u> | Use back-light when you put on the weight |
| | bi-on > | Use back-light always |
| RS-232C | -5-5½ / > | If weight is stable, transmit the data. |
| | <u> </u> | If weight is stable and after adding the weight, transmit the data after press button 'zero' key. |
| | ~5- <u>Ca</u> | Transmit the data contiunally. |
| | -5-P <u>-</u> | Communicate with PC |

8. Interface in Detail


This function is helpful to understand RS-232C Communication user setting. The following is the communication information of RS-232C.

RS-232C Port Connection




- → 8-BITASCII code
- → None parity
- → 1 stop bit
- → baud rate 9600

• USB INTERFACE(Device)




RS-232C Protocol



Transmission Data description

| DATA | Value(HEX) | Description |
|---------|----------------|---------------------------------------|
| SOH | 01h | Start of heading |
| STX | 02h | Start of text |
| STA | S(53h),U(55h) | S: Stable , U:Unstable |
| SIGN | -(2Dh),SP(20h) | Sign of the weight data |
| W5~W0 | | Weight data |
| UN1,UN2 | KG,LB | Unit of Weight |
| BCC | | Block check character exclusive or(^) |
| ETX | 03h | End of text |
| EOT | 04h | End of transmission |

COMMAND: DC1(0X11) SCALE->PC DATA FORMAT



BATTERY MAINTENANCE

LOW BATTERY WARNING

This product is a combination product dry battery and rechargeable battery.

When the battery is low the display shows the "LowbAt" sign.

You can replace the battery new one.

If rechargeable battery, please charge immediately.

You can shorten battery life.

If you still use the scale without replacing the battery the scale may provide incorrect result on measurement.

ERROR MESSAGE

| Error Message on Display | Description | Solution | | |
|--------------------------|---|--|--|--|
| Z-Err > | The "Z-Err" occurs when a current zero point has shifted from the last span calibration. | Please call your CAS dealer. | | |
| [Err > | When HIGH and LOW limit are set as the same or above maximum capacity it still shows "Err" message. | Please reset the maximum and minimum capacity. | | |
| d-Err > | The "d-Err" message will be shown when HIGH and LOW limits of comparison functions are set as inadequate unit value | Please reset the unit value setting again to be adequate. | | |
| Err 3 | The "Err 3" is an overload error. | Please remove the weight | | |
| LaïaAt) | The " LowbAt " is battery low. | Please change new battery. If rechargeable battery, please charge immediately. | | |

SPECIFICATIONS

MODEL: SWII

| Capacity | Dual Interval | Single | Dual Interval | Single | Dual Interval | Single | Dual Interval | Single |
|------------------------------|---|---|------------------|----------------------------------|------------------|--------------------------------|------------------|-------------------------------|
| | Max 1.5/3kg | Max 3kg | Max 3/6kg | Max 6kg | Max 6/15kg | Max 15kg | Max 15/30kg | Max 30kg |
| е | e=0.5/1g | e=1g e=0.5g e=0.2g e=0.1g | e=1/2g | e=2g e=1g e=0.5g e=0.2g | e=2/5g | e=5g e=2g e=1g e=0.5g | e=0.5/1g | e=10g e=5g e=2g e=1g |
| External Resolution | 1/3000 | 1/3000~ 1/30000 | 1/3000 | 1/3000~ 1/30000 | 1/3000 | 1/3000~ 1/30000 | 1/3000 | 1/3000~ 1/30000 |
| MAX Tare | -1.4995 kg | -2.999 kg | -2.999 kg | -5.998 kg | -5.998 kg | -14.995 kg | -14.995 kg | -29.990 kg |
| Display | 115 x 35 | 115 x 35 [mm] / 45 " x 15.5 " 6 digit LCD | | | | | | |
| Symbols | STABLE, ZERO, TARE, g, kg, lb, oz, Low Battery HI / OK / LO & PCS | | | | | | | |
| Keys | ZERO/ UNIT, TARE/ HOLD , MODE, FUCTION | | | | | | | |
| Functions | Weighing, Hold, Unit Conversion, Counting-Counting Sample Range : 10~100,200, 500 Weight Comparison Function : hi, ok, low Backlight ON/OFF Control Function | | | | | | | |
| Dimension s | 250 (W) x 281 (D) x 110 (H)[mm] / 984 (W) x 111 (D) x 43 (H)[inch] | | | | | | | |
| Platter size | 226 (W) x 187 (D)[mm] / 88.97 (W) x 73.62 (D)[inch] | | | | | | | |
| Weight | 1.8 kg | | | | | | | |
| Power | 1.5 V x 3 units (D size Battery), Pb 4 V4 A, 6 V Adapter | | | | | | | |
| Operation Time | Approx. 300 hours (Manganese Battery) / 600 hours (Alkaline at 20 °C /68 °F) / Backlight off | | | | | | | |
| Operating Temperatur e | -10 °C ~ +40 °C / 14 °F ~ 104 °F | | | | | | | |
| Option | 6V Adapter 500mA, Pb 4V4A, Rear Display, RS232, USB, SUS TRAY | | | | | | | |

^{*} Notice: Specifications are subject to change for improvement without notice.

RETAIL WEIGHING SOLUTION™



CAS BLDG., #1315, YANGJAE-DAERO, GANGDONG-GU, SEOUL, KOREA

TEL_ 82 2 2225 3500 FAX_ 82 2 475 4668 www.globalcas.com



9002-SWL-0033-0 2016.11